

OHD 981 957 905
BrookPark Landfill
6388 Kolthoff Drive CD20
Cleveland, Ohio 44142
Cuyahaga County 035

OHD 981 957 921
BrookPark Service Center
6400 Kolthoff Drive CD20
Cleveland, Ohio 44142
Cuyahaga County 035

OHD 981 957 913
Naiman Co/Caravan
6427 Eastland Road CD20
Cleveland, Ohio 44142
Cuyahoga County 035

Preparation of a work plan for OHD 980 704 191, Brook Park Sites, by Ecology and Environment revealed that there are three other sites that should be entered in CERCLIS and investigated separately. Because enough is known that the next step toward a site inspection, preparation of a work plan, is needed, no PA in the usual sense is required. This statement serves as a PA. Ecology and Environment was tasked today to prepare a work plan. Mark Bezel, of Ohio EPA, agreed with these actions.

US EPA RECORDS CENTER REGION 5



466343

#00974 NB

Med *NB*
6-25-87

OHD 981 957 905
BrookPark Landfill
6388 Kolthoff Drive CD20
Cleveland, Ohio 44142
Cuyahoga County 035

DME *DFA*
6/25/87 6/25/87

OHD 981 957 921
BrookPark Service Center
6400 Kolthoff Drive CD20
Cleveland, Ohio 44142
Cuyahoga County 035

OHD 981 957 913

Naiman Co/Caravan
6427 Eastland Road CD20
Cleveland, Ohio 44142
Cuyahoga County 035

Preparation of a work plan for OHD 980 704 191, Brook Park Sites, by Ecology and Environment revealed that there are three other sites that should be entered in CERCLIS and investigated separately. Because enough is known that the next step toward a site inspection, preparation of a work plan, is needed, no PA in the usual sense is required. This statement serves as a PA. Ecology and Environment was tasked today to prepare a work plan. Mark Besel, of Ohio EPA, agreed with these actions.

#00947 NB

